

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014707**Date Inspected:** 04-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	NA	CWI Present:	Yes	No			
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006	Component:	OBG				

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector Larry Viars was present during the times noted above for observations relative to the work being performed.

West of Bay 19-

This QA Inspector performed Magnetic Particle Testing (MT) verification of welds previously tested and accepted by ZPMC for OBG Segment 10BW welds. See MT report TL-6028 generated this date for additional information. The following welds were tested:

DP236-001-100, 102, 104, 105, 107, 109, 110, 113, 115, 117, 118, 120, 121, 121, 123, 125, 126, 128, 129, 131, 133, 134, 136, 137, 139, 141

DP263-001-100, 102, 104, 105, 107, 109, 110, 113, 115, 117, 118, 120, 121, 121, 123, 125, 126, 128, 129, 131, 133, 134, 136, 137, 139, 141

DP128-002-081, 083, 085, 086, 090, 091, 093, 094, 096, 099, 101, 102, 104, 106, 107, 109, 110, 112, 114

DP290-001-062, 064, 066, 067, 069, 071, 072, 074, 075, 077, 079, 080, 082, 083, 085, 087

DP101-001-063, 065, 068, 070, 073, 076, 078, 081, 084, 086

DP128-001-082, 084, 087, 092, 095, 097, 100, 103, 105, 108, 111, 113

DP155-001-101, 103, 106, 108, 111, 114, 116, 119, 122, 124, 127, 130, 132, 135, 138, 140

DP182-001-101, 103, 106, 108, 111, 114, 116, 119, 122, 124, 127, 130, 132, 135, 138, 140

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

documents.

Summary of Conversations:

Only general conversation between QA and QC occurred this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150 0042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Viars,Larry	Quality Assurance Inspector
Reviewed By:	McClendon,Timothy	QA Reviewer
